1121 Washington St. Newton, MA 02465 V/TTY 617.641.2802 FAX 617.641.2812 www.kmaccess.com info@kmaccess.com

## Common Access Errors in School Design & Construction

You can avoid common accessible design and construction errors. Be sure to review plans for the following access elements. (521 CMR is cited when it is more stringent than ADAAG.) You can see our Boston Society of Architects presentation on <u>Common Access Errors in School Design and Construction</u> on our website. Feel free to forward this to your colleagues and contractors.

- 1. Make all exterior <u>accessible routes</u> accessible. <u>521 CMR 22.1</u> (\*pdf)
- 2. Disperse accessible parking. 4.6.2
- 3. Provide an accessible, <u>exterior means of egress</u> to a public way. <u>521 CMR</u> <u>20.11.2</u> (\*pdf)
- 4. Provide automatic door openers on all <u>exterior entrance doors</u>. <u>521 CMR</u> <u>26.8.1a</u> (\*pdf)
- 5. Provide at least one leaf of <u>double doors</u> with 32" (min.) clear opening. 4.13.5
- 6. Provide more than one <u>elevator</u> in larger school buildings. <u>28 CFR 35 130</u>
- 7. Locate the <u>accessible route to the stage</u> within the assembly area. <u>521</u> <u>CMR 14.6</u> (\*pdf)
- 8. Provide <u>handrails on assembly area</u> aisles steeper than 5%. <u>521 CMR 24.5</u> (\*pdf)
- 9. Provide <u>integrated accessible seating</u> in assembly areas. <u>521 CMR 14.4</u> (\*pdf)
- 10. Make all toilet rooms accessible, including faculty and visitors. 4.1.3 (11)
- 11. Ensure that all <u>toilet centerlines</u> are 11.5"- 18.5" from the closest wall. 521 CMR <u>2.4.4</u> & <u>30.7.2 & 30.14.2</u> (\*pdf)
- 12. Ensure that <u>toilet flush valves</u> are located on the wide side of the toilet. 4.16.5
- 13. Avoid handrails and transaction counters as 'protruding objects.' 4.4.1

- Design ramps with slopes the least possible slope, never greater than 1:12.
  4.8.2
- 15. Ensure <u>construction</u> complies with your accessible design. <u>28 CFR Parts 35</u> & <u>36</u>

